

BEAUFORT County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
Beaufort County					
ATLANTIC SOFT DRINK CO INC	PETRO	UST	BLWM		Site ID # 00932. RBCA Classification 2BB3. Monitored Natural Attenuation.
BATTERY CREEK MAINTENANCE FACILITY	PETRO	UST	BLWM		Site ID # 10119. RBCA Classification 2BB3. Monitored Natural Attenuation.
BATTERY MARINA VILLAGE	PETRO	UST	BLWM		Site ID # 10440. RBCA Classification 3AC7. Approved Monitored Natural Attenuation (MNA Awaits).
BEAUFORT MAINTENANCE FACILITY	PETRO	UST	BLWM		Site ID # 10801. RBCA Classification 2BA7. Approved Monitored Natural Attenuation (MNA Awaits).
BEAUFORT PATROL FACILITY	PETRO	UST	BLWM		Site ID # 01056. RBCA Classification 3BF1. Conducting investigation/Risk Assessment.
BILLS COUNTRY STORE	PETRO	UST	BLWM		Site ID # 15888. RBCA Classification 2BB2. Free Product recovery only.
BIRD OIL COMPANY	PETRO	AGT	BOW		Monitored Natural Attenuation.
BLOCKERS GROCERY	PETRO	UST	BLWM		Site ID # 14310. RBCA Classification 3BD7. Approved Monitored Natural Attenuation (MNA Awaits).
BLUFFTON SHELL	PETRO	UST	BLWM		Site ID # 11727. RBCA Classification 2BB3. Monitored Natural Attenuation.
BURTON FIRE DISTRICT	PETRO	UST	BLWM		Site ID # 18202. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits).
CALLAWASSIE GENERAL STORE	PETRO	UST	BLWM		Site ID # 11719. RBCA Classification 3BF5. Inactive.
CALLAWASSIE GOLF COURSE	PETRO	UST	BLWM		Site ID # 05262. RBCA Classification 3BF1. Conducting investigation/Risk Assessment.
CAR CARE CLINIC	PETRO	UST	BLWM		Site ID # 12293. RBCA Classification 3AC3. Monitored Natural Attenuation.
CHAPMAN PROPERTY	PETRO	UST	BLWM		Site ID # 00974. RBCA Classification 3BA1. Conducting investigation/Risk Assessment.
CHARLESTON COCA COLA BOTTLING	PETRO	UST	BLWM		Site ID # 00913. RBCA Classification 2BB3. Monitored Natural Attenuation.
CIRCLE K 2705385	PETRO	UST	BLWM		Site ID # 17140. RBCA Classification 3BF1. Conducting investigation/Risk Assessment.
CIRCLE K 2705386	PETRO	UST	BLWM		Site ID # 17709. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits).
CIRCLE K 2705391	PETRO	UST	BLWM		Site ID # 17634. RBCA Classification 3AC5. Inactive.
CIRCLE K 2708100	PETRO	UST	BLWM		Site ID # 00992. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaits).
CLARENDON FARMS INC	PETRO	UST	BLWM		Site ID # 00927. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits).

10/28/2008

BEAUFORT County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
COLIGNY EXXON	PETRO	UST	BLWM		Site ID # 01052. RBCA Classification 3BF3. Monitored Natural Attenuation.
COUNTRY STORE	PETRO	UST	BLWM		Site ID # 09983. RBCA Classification 3AA8. Awaiting Funding.
CP'S GENERAL STORE	PETRO	UST	BLWM		Site ID # 12213. RBCA Classification 4AA3. Monitored Natural Attenuation.
DATAW ISLAND MARINA	PETRO	UST	BLWM		Site ID # 11901. RBCA Classification 3AC1. Conducting investigation/Risk Assessment.
DC USA - PINELAND (DC USA COASTAL, INC)	VOC	UNK	BLWM	SCD981477102	Assessment complete. Groundwater is discharging to drainage canal along Highway 278.
DC USA - POPE (DC USA COASTAL, INC)	VOC	S/L	BLWM	SCD987595873	BLWM File # 55062. In monitoring and remediation phases.
DOBBS BP	PETRO	UST	BLWM		Site ID # 14441. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
DOLPHIN HEAD GOLF COURSE	PETRO	UST	BLWM		Site ID # 00949. RBCA Classification 1D4. Active corrective action.
DOWNTOWN MARINA OF BEAUFORT	PETRO	UST	BLWM		Site ID # 01028. RBCA Classification 3AC5. Inactive.
DR TIRE	PETRO	UST	BLWM		Site ID # 16428. RBCA Classification 1D4. Active corrective action.
DRYCLEAN USA - BEAUFORT	VOC	UNK	BLWM	SCD981477102	BLWM File # 52460. In assessment and monitoring phases. Plume is discharging to drainage canals.
ENMARK 120	PETRO	UST	BLWM		Site ID # 01003. RBCA Classification 3BF3. Monitored Natural Attenuation.
FMR ADVANCE CLEANERS/DC USA	VOC	S/L	BLWM	SCD982131641	BLWM File # 53425. In assessment and monitoring phases.
FMR DRYCLEAN USA COASTAL, INC	VOC	S/L	BLWM	SCDRY005623	BLWM File # 56235. No activity at this time.
FMR. DRYCLEAN USA (MARKET PLACE)	VOC	S/L	BLWM	SCDRY005626	BLWM File # 56263. In monitoring and remediation phases. Plume is discharging to drainage canal.
FOLLY RD GROCERY	PETRO	UST	BLWM		Site ID # 00988. RBCA Classification 2BB3. Monitored Natural Attenuation.
FORMER ANNS GROCERY	PETRO	UST	BLWM		Site ID # 15523. RBCA Classification 3BF5. Inactive.
FORMER BEAUFORT MAINT FACILITY	PETRO	UST	BLWM		Site ID # 01057. RBCA Classification 2BA4. Active corrective action.
FORMER CUSTOM CLEANERS	VOC	OTHER	BOW		Site is in assessment phase.
FORMER GULF STATION	PETRO	UST	BLWM		Site ID # 15673. RBCA Classification 3BD1. Conducting investigation/Risk Assessment.
GRAYCO PROPERTY	VOC	S/L	BLWM	SCS123456924	BLWM File # 55066. In assessment and monitoring phases.
HAPPY MART 33 EXXON	PETRO	UST	BLWM		Site ID # 01021. RBCA Classification 1D2. Free Product recovery only.
HARBOUR TOWN YACHT BASIN	PETRO	UST	BLWM		Site ID # 11753. RBCA Classification 3BF5. Inactive.

BEAUFORT County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
HILTON HEAD BOATHOUSE LLC	PETRO	UST	BLWM		Site ID # 10193. RBCA Classification 3AC7. Approved Monitored Natural Attenuation (MNA Awaits).
HILTON HEAD COUNTRY CLUB	PETRO	UST	BLWM		Site ID # 09951. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits).
HILTON HEAD SECTION SHED	PETRO	UST	BLWM		Site ID # 01055. RBCA Classification 2BB3. Monitored Natural Attenuation.
HILTON HEAD SHELL	PETRO	UST	BLWM		Site ID # 12808. RBCA Classification 3BD5. Inactive.
ISLAND CAR WASH	PETRO	UST	BLWM		Site ID # 00990. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
ISLAND CHEVRON 50172	PETRO	UST	BLWM		Site ID # 00975. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits).
ISLAND TIRE SERVICE INC	PETRO	UST	BLWM		Site ID # 01005. RBCA Classification 3BD3. Monitored Natural Attenuation.
KALAMA SPECIALITY	VOC, METALS, BNA	S/L, SPL, STTF	BLWM	SCD094995503	BLWM File # 51903. In monitoring and remediation phases.
LADY'S ISLAND MARINA	PETRO	AGT	BOW		In assessment phase. Plume discharging to Coosaw River.
LARRYS TEXACO	PETRO	UST	BLWM		Site ID # 01001. RBCA Classification 3AA7. Approved Monitored Natural Attenuation (MNA Awaits).
LEMON ISLAND MARINA	PETRO	UST	BLWM		Site ID # 05302. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
LOBECO PRODUCTS INC.	VOC, PCB	PPL, S/L	BOW		Source remediation completed. Designing a ground-water recovery system. Completing assessment. Mixing Zone candidate.
LONG COVE CLUB ASSOCIATION	PETRO	UST	BLWM		Site ID # 12740. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaits).
MARINE CORP RECRUIT DEPOT BLDG 850	PETRO	UST	BLWM		Site ID # 15494. RBCA Classification 3BF3. Monitored Natural Attenuation.
MAUDES COUNTRY STORE	PETRO	UST	BLWM		Site ID # 12960. RBCA Classification 2AA4. Active corrective action.
MCAS AOC-C	VOC, METALS	S/L	BLWM	SC1750216169	Mop Wash Area. In RFI phase. No active groundwater monitoring.
MCAS COMMON TANKS INFO	PETRO	UST	BLWM		Site ID # 01062. RBCA Classification 3BF3. Monitored Natural Attenuation.
MCAS EX SERVICE STATION	PETRO	UST	BLWM		Site ID # 13575. RBCA Classification 3BF3. Monitored Natural Attenuation.
MCAS LAUREL BAY STATION	PETRO	UST	BLWM		Site ID # 15547. RBCA Classification 3BF4. Active corrective action.
MCAS OB/OD UNIT	VOC, OTHER	UNK	BLWM	SC1750216169	Open Burn/Open Detonation Units - Active units. Semi-Annual monitoring program in place.

BEAUFORT County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
MCAS SWMU 1 and 2	METALS	LF	BLWM	SC1750216169	SWMU 1-Fenced Hazard Area. SWMU 2-Lafrene Rd. Landfill. Sites are on small island surrounded by salt-water marsh. Possible UXO at SWMU 1. Investigation/monitoring suspended.
MCAS SWMU 12	METALS, VOC, OTHER	S/L	BLWM	SC1750216169	Former Eastern Fire Training Pits. In RFI phase. No active groundwater monitoring.
MCAS SWMU 18	VOC	OTHER	BLWM	SC1750216169	Active Crash Fire Rescue Training Area. Investigation on hold until unit/base closure. No active groundwater monitoring.
MCAS SWMU 3	METALS	LF	BLWM	SC1750216169	Borrow Pit Landfill. In CMS phase. Site is bounded by salt-water marsh. No active groundwater monitoring.
MCAS SWMU 4	METALS	LF	BLWM	SC1750216169	South East Point Disposal Area. Site is bounded by salt-water marsh. In RFI phase. Possible UXO onsite. Investigation suspended.
MCAS SWMU 5	VOC, P/H	PPL	BLWM	SC1750216169	Pesticide Residue Pit. In CMS phase. No active groundwater monitoring.
MCAS SWMU 6 & 14	METALS, VOC	LF, OTHER	BLWM	SC1750216169	SWMU 6 - Inert Landfill Seepage Trenches. SWMU 14 - Inert Landfill. In CMS. No active groundwater monitoring.
MCAS SWMU 8	METALS	LF	BLWM	SC1750216169	Kavieng Street Landfill. RFI phase. Groundwater monitoring system in place, but no active groundwater monitoring.
MCAS/1054 GARDENIA DRIVE	PETRO	UST	BOW		Site is in assessment phase.
MCAS/A-B TRANSFER PIPELINE RLS	PETRO	S/L	BOW		Site is in assessment phase. Leak from fuel transfer pipeline.
MCAS/DAY TANKS (551 & 865)	PETRO	AGT	BOW		In monitoring and remediation phases.
MCAS/EAST RAPID REFUEL PITS	PETRO	S/L	BOW		Site is in remediation phase.
MCAS/FUEL PIER TANKS (567&568)	PETRO	AGT	BOW		Free product recovery
MCAS/HANGER 414 (PETRO SPILL)	PETRO	S/L	BOW		Site is in assessment phase. Leak from fuel pipeline in front of Hanger 414.
MCAS/TANK FARM C	PETRO	AGT	BOW		In remediation.
MCAS/WEST PITS TRANSFER PIPELINE	PETRO	S/L	BOW		Site is in assessment phase. Leak from fuel transfer pipeline.
MCKIBBEN FIRESTONE	PETRO	UST	BLWM		Site ID # 18602. RBCA Classification 3BE2. Free Product recovery only.
MCLEOD PLANTATION	PETRO, PEST/HERB	UST, Other	BOW		Site is in assessment phase.
MCRD MWR DRY CLEANING FACILITY	VOC	S/L	BLWM	SC6170022762	SWMU 45. Investigation complete. Currently pilot-testing zero-valent iron injection.
MCRD/AVGAS PIPELINE	PETRO	S/L, AGT	BOW		In assessment phase.

BEAUFORT County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
MCRD/BLDG.4022	PETRO	UST	BOW		Site is in assessment phase.
MCRD/DEPOT FUEL FAC (BLDG 170)	PETRO, METALS	S/L, AGT	BOW		Site is in assessment phase. Contamination in the vicinity of BLDGs 155,139,170.
MORRIS VARIETY SHOP	PETRO	UST	BLWM		Site ID # 00996. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
MOSS CREEK PLANTATION	PETRO	UST	BLWM		Site ID # 12742. RBCA Classification 2BB3. Monitored Natural Attenuation.
NICKELPUMPER 213	PETRO	UST	BLWM		Site ID # 00993. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
NICKELPUMPERS 1	PETRO	UST	BLWM		Site ID # 00976. RBCA Classification 2BB2. Free Product recovery only.
OLD MALPHRUS CONSTRUCTION	PETRO	UST	BLWM		Site ID # 18453. RBCA Classification 3BD3. Monitored Natural Attenuation.
PALMETTO DUNES	PETRO	UST	BLWM		Site ID # 01022. RBCA Classification 2AB2. Free Product recovery only.
PANTRY 295	PETRO	UST	BLWM		Site ID # 00970. RBCA Classification 2BB5. Inactive.
PANTRY 3377	PETRO	UST	BLWM		Site ID # 10409. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaiti.
PANTRY 400	PETRO	UST	BLWM		Site ID # 12174. RBCA Classification 3BF3. Monitored Natural Attenuation.
PANTRY 408	PETRO	UST	BLWM		Site ID # 00995. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaiti.
PANTRY 430	PETRO	UST	BLWM		Site ID # 00991. RBCA Classification 2BB3. Monitored Natural Attenuation.
PANTRY 618	PETRO	UST	BLWM		Site ID # 00971. RBCA Classification 3BD3. Monitored Natural Attenuation.
PANTRY 917	PETRO	UST	BLWM		Site ID # 10815. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaiti.
PEOPLES EXXON	PETRO	UST	BLWM		Site ID # 15156. RBCA Classification 2AA7. Approved Monitored Natural Attenuation (MNA Awaiti.
PLANTATION STATION	PETRO	UST	BLWM		Site ID # 18038. RBCA Classification 2AA4. Active corrective action.
PORT OF BALDWIN MINES	METALS	S/L	BLWM	SCN000407725	BLWM File # 56944. In assessment and monitoring phases. Plume is discharging to Beaufort River.
SANTEE COOPER H H TURBINE PLANT	PETRO	S/L	BOW		In remediation.
SHELL FOOD MART STATION 101	PETRO	UST	BLWM		Site ID # 11733. RBCA Classification 2BB5. Inactive.
SILKEN WEBB FLOWER & GIFT	PETRO	UST	BLWM		Site ID # 15170. RBCA Classification 2AA1. Conducting investigation/Risk Assessment.

BEAUFORT County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
SINGLETONS AMOCO	PETRO	UST	BLWM		Site ID # 00978. RBCA Classification 2AA7. Approved Monitored Natural Attenuation (MNA Awaits).
SOMMERS 052	PETRO	UST	BLWM		Site ID # 12805. RBCA Classification 2BB3. Monitored Natural Attenuation.
SOUTH BEACH MARINA LLC	PETRO	UST	BLWM		Site ID # 14368. RBCA Classification 2AA4. Active corrective action.
SOUTH ISLAND PUBLIC SERVICE DISTRICT	PETRO	UST	BLWM		Site ID # 12899. RBCA Classification 3BD3. Monitored Natural Attenuation.
SOUTHERN GAS PARTNERS	PETRO	UST	BLWM		Site ID # 09518. RBCA Classification 3BF7. Approved Monitored Natural Attenuation (MNA Awaits).
SPEEDY FOOD MART #1	PETRO	UST	BLWM		Site ID # 01020. RBCA Classification 2BB3. Monitored Natural Attenuation.
SUNOCO 0623 1609 COOP2658	PETRO	UST	BLWM		Site ID # 01025. RBCA Classification 3AC7. Approved Monitored Natural Attenuation (MNA Awaits).
SUNOCO 0661 0174 COOP2660	PETRO	UST	BLWM		Site ID # 01027. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits).
TRIANGLE ICE CO	PETRO	UST	BLWM		Site ID # 18982. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
UST - UNKNOWN 15044	PETRO	UST	BLWM		Site ID # 15044. RBCA Classification 2BB4. Active corrective action.
VILLAGE STORE	PETRO	UST	BLWM		Site ID # 14941. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
WAMCHEM INC	VOC	PPL, SI	BLWM	SCD037405362	BLWM File # 51243. In monitoring and remediation phases. Plume is discharging to McCalley's Creek.
WEXFORD PLANTATION POA	PETRO	UST	BLWM		Site ID # 12148. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits).
WILLIAMS GARAGE & SERVICE STA	PETRO	UST	BLWM		Site ID # 12746. RBCA Classification 3AA6. Contacted.
WILLIAM'S GROCERY	PETRO	S/L, AGT	BOW		In assessment phase.
XPRESS LANE 1	PETRO	UST	BLWM		Site ID # 00984. RBCA Classification 3BF5. Inactive.
XPRESS LANE 10	PETRO	UST	BLWM		Site ID # 10906. RBCA Classification 3BD1. Conducting investigation/Risk Assessment.
Total for Beaufort	121				